Cato Water Control Structure




The levee has been breached in order to remove the old water control structure and replace it with the new one. The old pipe has been removed and work is moving forward.